

General Environmental Incident Summary

Incident: 4036 **Date/Time Notice:** 3/9/2016 1051 **DEM Incident No:**
Responsible Party: Oneok Rockies Midstream, LLC.
Date Incident: 3/5/2016 **Time Incident:** 1300 **Duration:** 1 minutes
County: Dunn **Twp:** 146 **Rng:** 95 **Sec:** 28 **Qtr:** NE
Lat: 47.44334 **Long:** -102.79160 **Method:** Interpolation from map
Location Description: 5 Miles north of Killdeer, ND

Submitted By: George Soto **Affiliation:** Optimized Process Design
Address: 25610 Clay Rd.
City: Katy **State:** TX **Zip:** 77493

Received By:

Contact Person: Nadia Kyrlova
2700 Lincoln Avenue SE
Sidney, ND 59270

Distance Nearest Occupied Building: 0.84 Miles **Release Contained:** Yes

Type of Incident: Fill hose came out of fill spout on tank during filling operations.

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 5.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Fill hose came out of fill spout on tank during filling operations.

Risk Evaluation:

none

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

none

Action Taken or Planned:

Diesel fuel soaked into soil in the area that received the spill. OPD immediately excavated the soil and placed into containment bags. Bags were placed in the designated contaminated soil storage containment and Western Choice Cooperative came to remove containment to dispose of contaminated soil.

Wastes Disposal Location: Western Choice Cooperative will pick up metal containment with excavated and bagged soil. OPD will get Bill of Lading for disposal verification.

Agencies Involved:

Updates

Date: 3/9/2016 ***Status:*** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 5 gallons of diesel fuel were released onto soils of the area. More follow-up needed.

Date: 3/17/2016 ***Status:*** Inspection

Author: Washek, Sandi

Updated Volume: 5.00 gallons

Notes:

Arrived on site at 11:30 a.m. Weather was overcast with snow, wind out of the NW at 20 mph, temperature 21 degrees F. Met with company rep on site and was informed that an NDDoH inspector had inspected the site last week. Spill was 5 gallons of diesel fuel. Looked at the site and reviewed the waste disposal report. The waste was sent to Renewable Resources. Additional information will be added.

Date: 4/28/2016 ***Status:*** Correspondence

Author: Cooper, Mike

Updated Volume:

Notes:

Talked with site safety supervisor. Material was put into a roll-off bin that will be tested and disposed of by Western Choice Cooperative. This spill is in the same location as General Incident 4037 and was disposed of and tested in a similar manner. Move to close the spill and site.